

0003

**SURFACE INSPECTION
COMPLIANCE REPORT**Date of Inspection: March 21, 2001Case Serial No.: UTU-075888Operator: Resource Design Solution (Joe Dunlop)Project Description: Mining GraniteLegal Description: SE¼ Sec 35, T. 12 S., R. 7 W.Field Office: FillmoreInspector: Larry GarahanaREPORT NARRATIVE (REFERENCE STIPULATIONS BY NUMBER OR TITLE)

The last inspection (3-7-01) found there had been a very small attempt at reclamation conducted on this site, but that it didn't show a good faith effort on the part of the operator to complete the reclamation as agreed upon previously.

This inspection I was accompanied by Tom Munson (DOGM), and we were at this site to confirm reclamation had not been completed, and to discuss what actions we may proceed with next. Upon arrival I noticed there had been no further work conducted since my inspection on March 7, 2001.

During our inspection Tom and I reviewed our case files, comparing dates, conversations, etc., and we determined that our offices have given RDS ample time and opportunity to remedy the problem without taking more formal actions, but it looks as though we're going to have to go in that direction.

I suggest we send RDS a letter of noncompliance, for their violations of the 3809 regs.

Signature of Inspector

Signature of Authorized Officer


0003

UTU-075888 Resource Design Solutionsd


Facing ~ northwest

Photo by: L Garahana

Photo shows: Area where RDS has removed material and was actively mining.



March 21, 2001





UTU-075888 Resource Design Solutions


Facing ~north

Photo by: Larry Garahana

Photo shows: Quarry wall where RDS has removed material (Tom for scale)

March 21, 2001





UTU-075888 Resource Design Solution

Facing approximately south

Photo by: L Garahana

Photo shows: Area that RDS agreed to reclaim in order to remain under five acres.

March 21, 2001